

	SUPPLIER QUALITY ASSURANCE REQUIREMENTS	
MATERIAL SUPPLIERS: QA1, QA2, QA3, QA4, QA5, QA6, QA7, QA8, QA9, QA10, QA11, QA12, QA13, QA14, QA15, QA16, QA17, QA18, QA19, QA20, QA21, QA23, QA24, QA25, QA26, QA27 (AS APPLICABLE)		
PROCESSING SUPPLIERS: QA1, QA2, QA3, QA4, QA5, QA6,QA7, QA8, QA9, QA10, QA12, QA13, QA14, QA15, QA16, QA18, QA19, QA20, QA21, QA22, QA23, QA24, QA25, QA26, QA27 (AS APPLICABLE)		
MROOR PACKING SUPPLIERS: QA2, QA6, QA7, QA8, QA9, QA11, QA12, QA14, QA16, QA19, QA20, QA21 (AS APPLICABLE)		
QA1	Clear, legible, unaltered Material Test Reports or authorized release certificates are required with all material shipments	
QA2	Suppliers shall furnish material that complies with all purchase order requirements documented on the Purchase Order	
QA3	All material processing records, testing records, and test reports must be retained for a minimum of 10 years and dispositioned per supplier's procedures.	
QA4	Supplier shall maintain a quality system that is in conformance with the Trident's Approved Quality System survey	
QA5	Trident shall have the right to inspect and/or test all material, at its source or destination, prior to acceptance	
QA6	Trident reserves the right to return, at the suppliers expense, any material found to be defective or out of compliance with applicable specifications	
QA7	Material must be packaged to protect from physical damage and exposure to water in transit or it may be subject to rejection by Trident	
QA8	Suppliers are required to flow down to sub-tiers any applicable requirements	
QA9	Supplier shall comply with all local, state, and federal laws and/or regulations in the performance of a purchase order	
QA10	All drawings, blueprints, patterns, and/or samples paid for by Trident or supplied by Trident shall not be used by the supplier except in the execution of a Trident purchase order	
QA 11	Safety Data Sheets (SDS) for material purchased shall be made available upon request	
QA12	Trident reserves the right to require its suppliers grant, us, our customer, our customer's customer and	
	regulatory agencies, the right of access to the supplier's premises for the purpose of verifying the quality of work, all applicable records, and/or materials at any level of the supply chain involved in the fulfillment of the purchase order	
QA13	Suppliers are required to maintain a measuring and test equipment calibration system. This system must have certifications that are traceable to N.I.S.T. and certifications must be maintained for a minimum of 10 years.	
QA14	Suppliers are required to provide Trident notification for nonconforming product or change of location of manufacturer and obtain approval prior to shipment.	



QA15	Suppliers are required to notify Trident of changes in: product and/or processes, suppliers, change in location of manufacturer, location, facilities, manufacturing, personnel qualifications and obtain approval from Trident
QA16	Traceability to the producing mill's heat/lot number and Trident's purchase order number must be maintained throughout all processing operations. Multiple heat/lots processed together must be separated prior to delivery to Trident in order to maintain traceability
QA17	Producing mill shall control the heat/lot identification of the product and maintain records for a minimum of 10 years and disposition per supplier's procedure.
QA18	Itisthesupplier'sresponsibilitytoinspectmaterialreceivedfromTrident toensurethatitiscorrect,and is notdamaged in any way, and is suitable forthe requestedprocesses
QA19	When acceptance authority media (AAM) is used to record the status of task/operations on product or product records during and/or upon completion of the development, manufacturing, modification, repair, and/or support processes, the organization shall establish appropriate controls for the media.
QA20	Trident monitors, evaluates, and reviews supplier performance.
QA21	Supplier's employees must be aware of their contribution to product conformity, product safety, and the importance of ethical behavior.
QA22	Processorsarerequired to provide a Certificate of Conformance orauthorized release certificate exhibiting conformance to Purchaseorder requirements.
QA23	Supplier must have a program for the prevention of possible counterfeit, suspect or unapproved materials.
QA24	Supplier must ensure employees are competent and have any required qualifications.
QA25	Supplier must communicate in writing all necessary information regarding the product or service accurately and in a timely manner.
QA26	Supplier shall make arrangements for establishing, implementing and maintaining a design and development process including planning, input, controls, outputs and changes.
QA27	Supplier shall use customer-designated or approved external providers, including process sources (e.g. special processes)